QP Code: 3519

		(3 Hours) [Total Marks: 8	
N.B.	(2) (3)	Question no. 1 is compulsory. Attempt any three questions out of remaining five questions. Assume suitable data if necessary. Figures to the right indicate full marks.	
1.	(a) (b) (c) (d)	short notes on:- Edge dislocation and its significance. Austempering Fatigue and significance of cyclic stress Powder metallurgy Eutectoid type of alloy phase diagram	20
2.	(5) (1)	State and explain various types of ingot defects and suggest remedies for these defects. Explain toughening mechanism in ceramics and write applications of ceramics.	10
3.	(a) (b)	Draw a neat and labelled Fe-FeC diagram at d state its limitations. How are composites classified? Explain the rule of mixtures in composites.	10 10
4.		Define Creep. Write about creep testing, data representation and analysis. Explain about the effect of alloying elements on ferrite, carbide, austenite and phase transformation.	10 10
5.	18 10	Draw and label a TTT diagram for 0.8% carbon steel Superimpose various Cooling curves on it and explain the processes. Explain the application of lever rule in the context of phase diagrams. Illustrate your answer with the help of neat sketches.	10 10
6.	(a) (b) (c)	e short notes on:- Martempering Normalising Flame hardening and induction hardening Carburizing	20

JP-Con. 12655-15.

muADDA.com

muADDA.com