

(CBSGS)(R-2012)

(3 hours)

[Total marks: 80]

N.B.: 1) Q. No. 1 is compulsory.

2) Attempt any three questions out of remaining five questions.

3) Assume suitable data if required.

Q1 a) Explain wire frame modeling, surface modeling and solid modeling. 10

b) Write a manual part program for finishing a forged component as shown in Fig. 1. Assume the spindle speed and feed for machining as 500 rpm and 0.3 mm/rev respectively. 10




Fig. 1

Q2 a) A Hermite cubic spline is defined by points (1, 1) and (6, 5), having tangent vectors as (0, 4) and (4, 0) respectively. Find the co-ordinates of parametric mid-point and slope at the same point. 10

b) Explain AS/RS and their types. 10

Q3 a) Find the transformed co-ordinates of a triangle A (50, 20), B (110, 20) and C (80, 60), if it is reflected about; i) X-axis and ii) Line $y = x$. 10

b) Explain the nature and role of CIM elements. 10

Q4 a) Find the transformation matrix which aligns vector K along positive z-axis with vector $V = aI + bJ + cK$. 10

b) Explain the major steps involved in rapid prototyping, list the various rapid prototyping technologies and explain Stereo-lithography in detail. 10

[P.T.O.]

FW-Con. 10597-16.

- Q5 a) Write a complete APT part program to machine the outline of the geometry and drill a hole as shown in Fig. 2. The component is 5 mm thick. The end mill used is 10 mm in diameter and suitable drill. Assume suitable speed and feed for machining. 12




Fig. 2

- b) Find the general transformation matrix N for window to viewport mapping. 8

- Q6 Write short notes on; 20

- Knowledge based Engineering
- Computer Aided Engineering
- CIM Hardware and Software
- Rapid Prototyping Applications